


FIG. 1








Fig. 3





IF USERS ARE EXPERIENCING FAST BUSIES WHILE TRYING TO MAKE A CALL FROM A CELL SITE THEN IT CAN BE DUE TO

- \*ANTENNAS IN THE CELL ARE DOWN
- \*CELL SITE IS DOWN COMPLETELY
- \*SEVERAL RADIOS IN THE CELL ARE NOT WORKING
- \*POWER SUPPLY TO THE CELL SITE IS DOWN

**END IF** 

Fig. 5



CELL 76 HAS 1 FACE CELL 76 HAS 3 RADIOS

ETC.

ETC.

ETC.

Fig. 6




Fig. 7